

FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management Solid Waste Section

UNIT	UNIT TYPE:														
Lined MSWLF		LCID	X	YW		Transfer		Compost		SLAS		COUNTY: Craven			
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		PERMIT NO.: 25-I			
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		FILE TYPE: COMPLIANCE			

Date of Site Inspection: 18 October 2012 Date of Last Site Inspection: 2 July 2012

<u>FACILITY NAME AND ADDRESS</u>: Cieszko Construction Company LCID Landfill

NC Hwy 101 Havelock, NC

GPS COORDINATES: N: 34.87495 E: 076.84969

FACILITY CONTACT NAME AND PHONE NUMBER:

Martin Cieszko 252.447.2096

FACILITY CONTACT ADDRESS:

Cieszko Construction Company PO Box 690

Havelock, NC 28532

E-mail: martin@cieszkoconstruction.com

PARTICIPANTS:

Attendant on site

Ray Williams; DENR-Solid Waste

STATUS OF PERMIT:

Active; Permit to Operate issued 5 April 2011 expires 8 May 2016. A complete permit review request for the next five-year phase of construction and/or operations is due on or before 8 February 2016. This application must comply with the rules and regulations in effect at the time of the application.

PURPOSE OF SITE INSPECTION:

Comprehensive Facility Inspection

STATUS OF PAST NOTED VIOLATIONS:

None applicable

OBSERVED VIOLATIONS:

None

ADDITIONAL COMMENTS:

- 1) This facility is a Land Clearing and Inert Debris (LCID) Landfill and is permitted to receive land clearing waste, yard trash, untreated and unpainted wood, uncontaminated soil, and inert debris such as unpainted rock, brick, concrete, and concrete block.
- 2) Proper signage has been posted and is being maintained at the entrance to the landfill indicating the permit number, list of permitted and non-permitted wastes, and the facility emergency contact number.
- 3) The site is secured with two locked gates. One located at the property entrance and another at the facility entrance and has controlled access for safety.
- 4) The access road to the facility is of all weather construction and is being managed properly at this time.
- 5) The sideslopes have a well-established cover crop of native warm season grasses and are being maintained at a slope not greater than 3:1. No areas of erosion were noted during this Facility Compliance Inspection.
- 6) This facility has highly visible, permanent, edge-of-waste markers in place delineating the landfill waste disposal footprint.

FACILITY COMPLIANCE AUDIT REPORT

Division of Waste Management Solid Waste Section

25I-20121018INSP

Page 2 of 2

- 7) The soil sedimentation and erosion control measures were reviewed and no off-site erosion was noted during this Facility Compliance Inspection.
- 8) The waste type being disposed is LCID waste only. There were no unacceptable waste streams noted during this Facility Compliance Inspection.
- 9) The active working area is compact and well managed.
- 10) Soil is stockpiled adjacent to the landfill and the active working face for use as cover.
- 11) The active working area is being covered monthly or when it reaches one acre in size, whichever occurs first.
- 12) The Facility attendant was working on compacting and re-sloping the eastern sideslope during this Facility Compliance Inspection.
- 13) Digital photographs were taken during this Facility Compliance Inspection.

Please contact me if you have any questions or concerns regarding this Facility Compliance Inspection Report.

Tay Williams

Ray Williams; Environmental Senior Specialist Phone: 252.948.3955 E-mail: ray.williams@ncdenr.gov

Regional Representative

Delivered on: 30 October 2012 by	X	Electronic delivery	US Mail	Certified No. []

cc: Dennis E Shackelford; Eastern District Supervisor/SWS: <u>dennis.shackelford@ncdenr.gov</u>
Jessica Montie; Chief Compliance Officer/SWS: <u>jessica.montie@ncdenr.gov</u>

C: \2012\Craven\Facilities\25-I\Audits\25I-20121018INSP NCDENR CARA Portal: https://edm.nc.gov/DENR-Portal/